





Thread Turning Directions


External Right-Hand (RH) Threading



External Left-Hand (LH) Threading



Internal Right-Hand (RH) Threading



Internal Left-Hand (LH) Threading

